

RELEASEnotes

Perception & GEN Series firmware V6.14.10323

These release notes are:

Perception:

from V6.12.10124 to V6.14.10323

GEN series firmware:

from V6.12.10124 to V6.14.10323

Firmware release notes will no longer be available as separate release notes as the firmware and its update process is now an integral part of the software.

Supported/Tested Windows 32 bit versions:

- Windows XP Service Pack 3
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate

Supported/Tested 64 bit versions:

- Windows XP Service Pack 2
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate

Supported/Tested Genesis High Speed platforms:

- GEN7t
- GEN16t
- GEN5i
- GEN2i
- LIBERTY4
- LIBERTY8

All Perception versions require Dot Net Framework V4.0 which will be distributed with the install and is also available for download on the internet.

All Perception versions now also require a Microsoft Direct3D® capable graphics card.

RELEASEnotes

The following options are part of this version:

- 826-026300 Multiple Workbooks
- 826-026200 Multiple Exports formats
- 826-026900 Multiple Mainframes
- 826-026600 Analysis (Formula database)
- 826-026700 Reporting & Word Reporting
- 826-027300 SOAP & RPC Interface
- 826-027400 Video Playback
- 826-032500 CSI Runtime
- 826-032700 Advanced High Voltage/High Power analysis (STL)
- 826-033600 Customized Info sheets
- 826-034400 HP-HV Automated Analysis
- 826-034900 BE256 / MultiPro Control
- 826-026800 Basic FFT
- 826-036300 Enterprise Edition
- 826-035500 HVIA
- 826-033000 Sequencer

RELEASEnotes

The following features have been added:

Perception:

- 9362 Smart Units Request - mmHg
- 9752 GEN2i: Add meters for Live and Review (calculators)
- 9754 GEN2i: Add Lock function
- 9755 GEN2i: Add One touch upgrade function for both Perception as well as embedded software
- 9758 Add a function to REBOOT connected hardware
- 9863 Add dynamic image interface to report engine
- 9871 Perception now uses Direct3D
- 9872 Perception display performance when using multi monitor improved by using Direct3D. System requirements are checked when starting
- 9899 Perception uses .NET Framework 4.0
- 9908 Add filter functions to Perception Analysis option / Formula database
- 9920 Perception install installs English manuals
- 9957 BE3200 USB optical RS232 driver is automatically installed by Perception
- 9976 Perception has been verified to work with Office2010 and Office 2010 x64
- 10017 French, Chinese and Japanese manuals installs added to CD
- 9479 RPC - Feature Enhancement Requests

GEN Series firmware:

- 9760 Notify hardware failures to Perception
- 9987 New 1GB SODIMM are now supported in 1MS/s boards

RELEASEnotes

The following improvements have been made:

Perception:

- 4166 Release candidates & Beta version should warn customer this version STOPS working in xx days.
- 9676 Scrolling Display doesn't work very well on a single core, non hyper threading CPU
- 9723 Various UI not compliant with Windows guidelines
- 9757 GEN2i: Improve default print layout
- 9773 GEN2i : Hardcode a drive performance limit for the Samsung drives into the software
- 9789 GEN2i: In Review we should display the name of the recording being displayed / loaded
- 9897 Ambiguous message about network performance

GEN Series firmware:

- 8242 Re-synchronizing IRIG/GPS and Master/Slave while recording if signal is lost
- 9456 Slave should not show time on front panel
- 9845 FAN's that are not rotating are notified to the user
- 9846 Over temperature on any of the Gen Series boards is now notified to the user
- 9847 Batteries need a re-learn procedure to keep the capacity reading accurate (Service PMB update required)
- 9848 Unexpected sudden shutdown (Service PMB update required)
- 9949 Memory test should show activity on the terminal output

RELEASEnotes

The following errors have been fixed:

Perception:

- 4161 Scroll Speed Options Missing
- 8507 Scroll speed change misses one or two steps
- 8720 Fiber Status table header distorted with 120 DPI
- 8961 FFT display annotation font in report cannot be changed and / or is wrong
- 9594 X2 position of a Slope Marker added via a slope cursor cannot be set via a data source
- 9599 Looks like Perception does not always unload fully from PC when you exit.
- 9628 Scrolling display falls behind in time and has time axis errors when using 4 monitors
- 9666 Remove the hide Y-annotation option
- 9684 Perception crashes when resizing display
- 9692 Sweep count is enabled after changing sweep length in acquisition control
- 9727 GEN2i: Strange side effects when printing report without active trace
- 9730 Instrument Panel Save Settings does not work correctly, see also 9728
- 9733 Created new GROUPS but did not show up in pull down menu for CONTROL window
- 9734 Timer message in wrong language
- 9738 Perception can't open NRF files
- 9746 Perception GUI doesn't look correct when using 120DPI
- 9748 No Perception Free Viewer or Perception Offline shortcut with 64-bit install
- 9749 Scrolling Display problems at sample rates less then 100S/s using Gen Series mainframes
- 9774 Sequencer sheet does not load setting back correct
- 9783 Loading workbench with secondary workbook is not correct
- 9795 Offline configuration only has old LDS part numbers listed
- 9796 Liberty battery hot plug replacement causes Perception to show batteries in incorrect order
- 9809 Sheet manager gets confused and shows sheet duplicates
- 9813 Red cross in channel trigger settings when disconnecting mainframe
- 9821 Drawing problems display when adding 1 point to an existing user waveform data source
- 9822 GEN 2i - GUI strange reading of time
- 9858 Performance Test shows incorrect OS

RELEASEnotes

- 9869 Gen2i GUI zoom window does not appear / hide correctly
- 9877 Control panel fields not active after mode switch
- 9882 GEN2i: When selecting Apply in the scaling units, the selected Unit is added to the list
- 9883 Live display should not scroll or scope when the display is not visible
- 9885 Network license not released when exiting Perception
- 9886 Perception crash when running on Gen2i and switch to classic Perception UI
- 9893 Continuous data rate incorrect when using timer/counter, event channels or CAN channels
- 9894 Continuous data rate not updated when enabling/disabling timer/counter, event channels or CAN bus channels
- 9901 GEN2i reload factory settings do not load acquisition mode
- 9903 Display setup annotation and grid looks strange
- 9906 GEN2i: Crash after NOT entering a new recording number
- 9907 The data sources start and end times of a display are not correctly updated.
- 9927 Perception doesn't update properly when table is set to auto size
- 9929 The NRF Export function doesn't release the created files under Windows XP 32 bit environment
- 9934 Perception crashes when it receives hundreds of notifications rapidly
- 9937 Perception 64 runs with a dongle that does not have the Enterprise option activated
- 9945 Perception - Stat Stream data display rates START versus SINGLE SHOT
- 9948 Remove German translation from Perception installation
- 9952 No change in instrument meters when load an old recording
- 9953 No export options available
- 9968 Perception hangs at startup when trying to find storage location
- 9971 The delta values of the cursors in GEN2i are not the same on the GUI as in the generated report
- 9974 Data cannot be loaded when administrative information contains invalid characters
- 9977 Perception crashes when hardware settings contain invalid characters
- 9978 Red cross when selecting Keyboard Control on instrument Panel
- 9980 Slow start of recording when a lot of meters are used
- 9983 Drag drop trace in instrument panel duplicates channel
- 9985 Perception standard GUI meter blinks when drawing values.

RELEASEnotes

- 9988 Huge experiment file on Data Example DVD cannot be opened
- 9989 Empty trigger position causes crash in perception
- 9990 double signal on GEN 2i when overlay signals
- 9991 Display setup is not loaded when using load recording from file menu and selecting to load in a new display
- 9994 Some printers cause Perception to crash on startup
- 9996 Print settings list incorrect continuous rate when dual storage mode is used
- 9997 Multiple mainframes with at least 1 event channel board may result in crashes or data storage remaining active when acquisition stops
- 9998 GEN 2i meters should be ON by default and also should be ON after loading factory defaults
- 10002 Meter content not cleared when associated channel is switched off
- 10005 GEN2i: Load FACTORY DEFAULTS should also load defaults for display and go to PAUSE
- 10006 GEN2i: Scrolling display does not follow the actual data on the BNC real-time
- 10007 GEN2i missing scroll speeds and scroll speeds are very irregular
- 10010 Event & CAN traces sometimes not shown in live display
- 10012 Setting "External clock divider" not enabled/selectable.
- 10020 Crash when using X-Shift function with data source which has no sweeps
- 10021 GEN2i load user defaults behavior is wrong
- 10022 Long sweeps times give no visible feedback in display until sweep is finished.
- 10023 Formula using unary minus might not update when value or data changes
- 10024 Loading NSS file with invalid block allocation table can result in crash
- 10025 Some sheets are shown when startup behavior is set to Don't Load
- 10031 Recording not stoppable after START
- 10032 Perception crashes when switching from live to review or vice versa
- 10034 GEN2i Instrument panel: Active page is lost after loading factory defaults
- 10037 Live display draws incorrect when slope is falling
- 10039 RC3 cannot connect to a configurator mainframe but v6.12 can
- 10040 Layout problem dialog Edit Item Displays for defining report to word setup
- 10046 Loading workbench using RPC results in crash when Perception is recording
- 10052 Traces sometimes not drawn on printout when display in Review Sweep mode

RELEASEnotes

10055 On a report, the scaling of the X-axis of a Spectral Display is not correct

GEN Series firmware:

- 8510 Dead battery in Liberty leads to useless information displayed
- 9584 Low sample rate is clipped to binary maximum rate even when running in decimal time base
- 9797 When 1 battery doesn't charge anymore, no batteries charge anymore (Service PMB update Required)
- 9799 Added battery notification when only 10 minutes operation time is remaining
- 9800 Added orderly shutdown with data save and recording close at end of battery operation (Service PMB update required)
- 9802 Battery capacity reported wrong (Service PMB update required)
- 9803 Charging batteries could switch rapidly between 2 batteries (Service PMB update required)
- 9804 Unexpected crashes in PMB software (Service PMB update required)
- 9806 Liberty front panel alerts on 25% and 10% remaining battery capacity.
- 9824 Batteries sometimes need external charger to be re-activate after an extreme discharge cycle (Service PMB update required)
- 9864 Battery pendeling while charging due to temperature (Service PMB update required)
- 9925 Liberty adds memory test failure markers to recording
- 9928 Offline configuration recorders report incorrect embedded software version
- 9936 GEN Series acquisition time jumps 32 seconds (4 times 8 seconds) after power on
- 9950 Digital Event Board Timer/Counter does not take binary rate into account
- 9958 Add recorder serial number to driver logging
- 9969 Memory test can fail when system is set to Pause/Review mode
- 10001 Notification when running in pause that storage is prioritized above live data
- 10003 GEN5i does not monitor second multiplexed fan feedback
- 9764 New 2GB SODIM fails in 100MS/s boards

RELEASEnotes

HBM GmbH

www.hbm.com

Email: info@hbm.com

Tel. +49 6151 803-0

Fax +49 6151 803-9100

measure and predict with confidence

