

RELEASEnotes

Perception & GEN Series firmware V6.16.11067

These release notes are:

Perception:

from V6.14.10323 to V6.16.11067

GEN series firmware:

from V6.14.10323 to V6.16.11067

Firmware release notes will no longer be available as separate release notes as the firmware and its update process is now an integral part of the software.

Supported/Tested Windows 32 bit versions:

- Windows XP Service Pack 3
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate SP1

Supported/Tested 64 bit versions:

- Windows XP Service Pack 2
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate SP1

Supported/Tested Genesis High Speed platforms:

- GEN7t
- GEN16t
- GEN5i
- GEN2i
- LIBERTY4
- LIBERTY8

All Perception versions require Dot Net Framework V4.0 which will be distributed with the install and is also available for download on the internet.

All Perception versions now also require a Microsoft Direct3D® capable graphics card.

RELEASEnotes

The following options are part of this version:

- 826-026300 Multiple Workbooks
- 826-026200 Multiple Exports formats
- 826-026900 Multiple Mainframes
- 826-026600 Analysis (Formula database)
- 826-026700 Reporting & Word Reporting
- 826-027300 SOAP & RPC Interface
- 826-027400 Video Playback
- 826-032500 CSI Runtime
- 826-032700 Advanced High Voltage/High Power analysis (STL)
- 826-033600 Customized Info sheets
- 826-034400 HP-HV Automated Analysis
- 826-034900 BE256 / MultiPro Control
- 826-026800 Basic FFT
- 826-036300 Enterprise Edition
- 826-035500 HVIA
- 826-033000 Sequencer

RELEASEnotes

The following features have been added:

Perception:

10158 Add software support for all variants of new 16 & 32 channel acquisition modules

10054 Add HIC functions to formula database

10066 XY display for GEN2i and Perception

10100 Add double click action to Manager Sheets dialog to load or remove a sheet

GEN Series firmware:

10159 Add firmware support for all variants of new 16 & 32 channel acquisition modules

10072 Add time marker when IRIG signal gets restored including listing of the detected time deviation between IRIG and mainframe time.

10073 When changing amplifier span we auto adjust the trigger levels to a lower value, this causes hysteresis to become too small

RELEASEnotes

The following improvements have been made:

Perception:

10016 Add the maximum disk speed in the recording file

GEN Series firmware:

10015 Add suspend and pause notification in recording file

8095 Notify overall storage progress from Genesis to Perception.

RELEASEnotes

The following errors have been fixed:

Perception:

- 2061 Storage gets slower when more sweeps are added.
- 7941 Network dongle / HASP key cannot be updated from network PC
- 9593 Perception performance decreases over time and will stop working eventually.
- 9784 Power button doesn't shutdown GEN2i
- 9832 GEN2i: LIVE display does not show data
- 9921 GEN2i desktop shortcut to instrument panel manual must be updated during install
- 9975 Auto scaling Y-axis Display problem.
- 10018 Size of event traces not loaded back from workbench and preferences
- 10033 Deselecting GEN and Liberty firmware updates in preferences not remembered
- 10041 Automation Process Display does not always work when working with multiple workbooks
- 10044 Count field is grayed out when selecting multi sweep mode.
- 10045 Possible to move hidden horizontal cursors in FFT
- 10047 Saved Spectral Display is always forced to be linked when reloaded
- 10057 Using same channel from 2 different recordings result in exact same FFT in Spectral Display
- 10061 When a recording is loaded as active in advanced Perception, it cannot be deleted later in Instrument Panel (GEN2i)
- 10077 Changing the grid's vertical divisions messes up Y-t display when zoomed
- 10079 Review to any other user-mode switch doesn't work
- 10082 Perception should notify when firmware cannot be upgraded
- 10089 Sample rates in Acquisition Control Panel not updated when switching decimal/binary
- 10092 With MultiPro data, Perception 6.14 never releases 1st recording
- 10101 Universal Amplifier picture for Current Input coupling not correct
- 10102 Perception freezes on every other trigger
- 10105 Canned Reports not loading properly and saved incorrectly
- 10106 GEN2i: Starting by double clicking an advanced saved VWB crash application
- 10108 Enable/Disable symbol not shown in spreadsheet
- 10120 Scroll speed set to 10ms/div instead of 1s/div when doing GEN2i factory default settings

RELEASEnotes

- 10125 Continuous data rate overview doesn't update when switching sample width
- 10127 Time counter icon in hardware tree must be changed
- 10133 Duplicate sheet ignores several components
- 10146 Perception crashes when closing the application while replay in display is active
- 10148 Perception can crash when event channels are displayed and subscriptions are canceled
- 10150 Error in (Re-) Loading Perception Recordings - ABB Sweden report
- 10151 Power recovery does not reload Display en Meterinfo on Instrument panel
- 10160 Perception 6.14 firmware upgrader cannot upgrade minimum mode mainframe
- 10164 Enterprise dongles should also work as enterprise software on 32Bit Perception versions

GEN Series firmware:

- 9914 GEN2i BIOS: Display voltage should be set to 5V
- 9993 IRIG Resync causes permanent master time base frequency error when a completely different IRIG signal is connected.
- 10137 Data storage and network performance degrades tremendously when suspends are occurring and even crashes mainframe

RELEASEnotes

HBM GmbH

www.hbm.com

Email: info@hbm.com

Tel. +49 6151 803-0

Fax +49 6151 803-9100

measure and predict with confidence

