



These release notes are from V6.01.9076 to V6.02.9140

### 1.1 Supported/Tested Perception versions:

- Tested with Perception V6.02.9140

### 1.2 New features

### 1.3 The following errors have been fixed (Testtrack records):

9233 Fixed IP address lost after upgrading embedded software.

9292 Interface module hangup when creating continuous data recording with triggers

9302 Upgrading firmware after JTAG procedure doesn't update CPU\_BAK

9312 Bridge Plus boards fail balance and shunt cal

9319 Diagnostics should be send immediately after loading settings has finished

9320 Triggering on 100MS/s recorder can result in trigger prior to the recording start (neg trigger times)

9323 Sometimes GEN series mainframe becomes unresponsive unexpectedly.

9324 Incorrect division of available PC buffer space might slow down recording storage on PC.

9340 Loading a .pVWB sometimes results in lost settings on GEN series mainframes.

9344 Slow storage of recoding

9346 GEN series mainframes keep acquisition memory occupied when an unexpected disconnect occurs during recording of sweeps.

9348 Data abort on digital event module due to running out of blocksets.

Release Notes