

RELEASEnotes

GEN Series firmware V6.12.10167

These release notes are from V6.12.10124 to V6.12.10167

Supported/Tested Perception versions:

- Perception V6.12.10124
- Perception V6.12.10124 64-bit

Supported/Tested Genesis High Speed platforms:

- GEN7t
- GEN16t
- GEN5i
- GEN2i

The following errors have been fixed:

Problem Report	9764	New 2GB SODIM fails in 100MS/s boards
----------------	------	---------------------------------------

LIBERTY & GEN Series firmware V6.12.10124

These release notes are from V6.06.9337 to V6.12.10124

Supported/Tested Perception versions:

- Perception V6.12.10124
- Perception V6.12.10124 64-bit

Supported/Tested Genesis High Speed platforms:

- GEN7t
- GEN16t
- GEN5i
- GEN2i
- LIBERTY4
- LIBERTY8

The following features have been added:

New Feature	9664	Output the recording active status on the D-connector
-------------	------	---

RELEASEnotes

The following improvements have been made:

Usability improvement	9664	The output D-connector on LIBERTY can now be used to detect recording active status
-----------------------	------	---

The following errors have been fixed:

Problem Report	9772	Settings may be lost when DOWNGRADING 6.10 to an earlier version
Problem Report	8089	Kontron Fiber Ethernet PMC does not pass a "coldboot".
Problem Report	9622	Remove FPGA warnings for Liberty 4slot mainframe
Problem Report	9638	LIBERTY basic bridge does not allow switching of calibration source. This may cause problems when doing bridge shunt verification.
Problem Report	9663	Gen2i Fan tachometer sometimes indicated double actual speed
Problem Report	9685	First acquisition times/position incorrect after setting system in pause mode

RELEASEnotes

HBM GmbH

www.hbm.com

Email: info@hbm.com

Tel. +49 6151 803-0

Fax +49 6151 803-9100

measure and predict with confidence

