RELEASEnotes

ISOBE5600 Series firmware V2.00.10091

These release notes are from V1.10.8037 to V2.00.10091

Supported/Tested Perception versions:

- Perception V6.10.10098
- Perception V6.10.10098 64-bit

Supported/Tested ISOBE5600 platforms:

ISOBE5600m Memory

The following features have been added:

New Feature Control the ISOBE5600m Memory from the Perception software

The following improvements have been made:

The following errors have been fixed:

Problem Report 8844 100V Range is lost after power on



RELEASEnotes

HBM GmbH

www.hbm.com Email: info@hbm.com Tel. +49 6151 803-0 Fax +49 6151 803-9100



xxxxxx-x.0 en