

# RELEASEnotes

## ISOBE5600 firmware V2.00.12339

These release notes are:

ISOBE5600 firmware:

from V2.00.10116 to V2.00.12339

### Supported/Tested Windows 32 bit versions:

- Windows XP Service Pack 3
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate SP1
- Windows 8 Pro

And Windows Updates until 11<sup>th</sup> September 2012.

### Supported/Tested 64 bit versions:

- Windows XP Service Pack 2
- Windows Vista Business SP2
- Windows Vista Ultimate SP2
- Windows 7 Ultimate SP1
- Windows 8 Pro

And Windows Updates until 11<sup>th</sup> September 2012.

### Supported/Tested Perception versions:

- Perception 6.30.12335
- Perception Enterprise x64 6.30.12335

# RELEASEnotes

The following errors have been fixed:

10970 ISOBE56005600 stops responding when connected using Perception

# RELEASEnotes

## HBM GmbH

[www.hbm.com](http://www.hbm.com)

Email: [info@hbm.com](mailto:info@hbm.com)

Tel. +49 6151 803-0

Fax +49 6151 803-9100

measure and predict with confidence

